

Fig. 2




Fig. 3




Fig. 5




Fig. 4




Fig. 8




Fig. 9




Fig. 6




Fig. 7


```

graph TD
    A[PROVIDE CURABLE ADHESIVE] --> B[PROVIDE INDEXING MEANS]
    B --> C[PROVIDE APPLICATION MEANS]
    C --> D[PROVIDE SOURCE OF DIES]
    D --> E[PROVIDE ATTACHING MEANS]
    E --> F[PROVIDE CONTROL MEANS]
    F --> G[OPERATE CONTROL MEANS TO CAUSE ADHESIVE TO BE APPLIED TO EACH LEAD FRAME AND TO ATTACH EACH DIE TO A LEAD FRAME]
  
```

Fig. 11